



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## FID 407: Bosch MEDC17 TC17XX BENCH [SM2 ONLY]

### Overview

Family for reading and writing Bosch MEDC17 ECUs

**Module:** Bosch MEDC17 TC17XX BENCH [SM2 ONLY]

**Supported MCUs:** TC1724, TC1728, TC1762, TC1766, TC1767, TC1782, TC1792, TC1793, TC1796, TC1797

### Supported features

Universal module for Bench reading and writing for Bosch MEDC17 ECUs based on TC17XX MCUs.

Allows reading and writing flash and EEPROM on the bench with auto detection of MCU type and file size. Checksum fix is performed on writing.

### Attention!

- Module **works only** with **Scanmatik SM2** or **SM2 Pro**.
- This FID is not suitable for cloning ECU because there are protected OTP sectors. Also sectors (0x10; 0x20) are skipped during writing operation in order to avoid bricking ECUs.
- On some ECUs checksums calculation may take a long time. It depends on the configuration of your computer.
- In case of an identification error, check your connection, and also change the places of the GPT wire.
- All tested adapters with automatic power management with wires for the GPT signal output available by the link below:

<http://archive.powertuner.net/bitbox/help/Adapters.pdf>



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Table of Contents

<b>Alfa Romeo</b> .....	<b>12</b>
EDC17C69 TC1793 Version 1.....	12
EDC17C69 TC1793 Version 2.....	12
EDC17C69 TC1793 Version 3.....	12
<b>Ashok leyland</b> .....	<b>13</b>
EDC17CV54 TC1767 .....	13
<b>Aston Martin</b> .....	<b>14</b>
ME17.8.31 TC1797.....	14
<b>BAJAJ KTM</b> .....	<b>15</b>
M17.8.42 TC1762 .....	15
<b>BAW</b> .....	<b>16</b>
EDC17CV54 TC1767 .....	16
<b>BMW</b> .....	<b>17</b>
DCU17PC42 TC1724.....	17
EDC17C06 TC1766 .....	17
EDC17C41 TC1797 .....	17
EDC17C50 TC1797 .....	18
EDC17C76 TC1793 .....	18
EDC17CP02 TC1766 .....	18
EDC17CP09 TC1796 .....	19
EDC17CP45 TC1797 Version 1 .....	19
EDC17CP45 TC1797 Version 2 .....	19



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17CP49 TC1797 .....	20
ME(V)17.2.1 TC1796 .....	20
MEV17.2 TC1766 .....	20
MEVD17.2 TC1797 .....	21
MEVD17.2.3 TC1793 .....	21
<b>BMW Motorrad .....</b>	<b>22</b>
ME17.2 TC1797 .....	22
ME17.2.4 TC1793 .....	22
<b>BRP.....</b>	<b>23</b>
ME17.8.5 TC1762 .....	23
<b>CFMoto.....</b>	<b>24</b>
ME17.8.10 TC1728.....	24
<b>China .....</b>	<b>25</b>
ME17.6.8 TC1762 .....	25
ME17.8.8/17.8.8.1/17U6/UP6 TC1728/1782 .....	25
<b>Citroen .....</b>	<b>26</b>
EDC17CP11 TC1796 .....	26
ME17.9.53 TC1782.....	26
MED17.4.4 TC1793 .....	26
<b>Claas.....</b>	<b>27</b>
EDC17C53 TC1767 Version 1.....	27
EDC17C53 TC1767 Version 2.....	27



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

<b>Dacia</b> .....	<b>28</b>
EDC17C42 TC1767 .....	28
EDC17C84 TC1782 .....	28
<b>Deutz</b> .....	<b>29</b>
EDC17C53 TC1767 Version 1.....	29
EDC17C53 TC1767 Version 2.....	29
EDC17CV54 TC1767 .....	29
<b>DongFeng</b> .....	<b>30</b>
EDC17C63 TC1724 .....	30
EDC17CV54 TC1767 .....	30
MED17.4.4 TC1793 .....	30
<b>Doosan</b> .....	<b>31</b>
EDC17CV54 TC1767 .....	31
<b>Farmtrac</b> .....	<b>32</b>
EDC17C63 TC1724 .....	32
<b>Fiat</b> .....	<b>33</b>
EDC17C69 TC1793 Version 1.....	33
EDC17C69 TC1793 Version 2.....	33
EDC17C69 TC1793 Version 3.....	33
EDC17C84 TC1782 .....	34



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

<b>Ford</b> .....	<b>35</b>
DCU17PC43 TC1724.....	35
EDC17C10 TC1797 .....	35
EDC17C70 TC1793 .....	35
MED17.0 TC1767 .....	36
MED17.0.1 TC1767 Version 1 .....	36
MED17.0.1 TC1767 Version 2 .....	36
MEDG17.0 TC1797.....	37
<b>Foton</b> .....	<b>38</b>
EDC17C63 TC1724 .....	38
<b>Great Wall</b> .....	<b>39</b>
EDC17C53 TC1767 Version 1.....	39
EDC17C53 TC1767 Version 2.....	39
EDC17C63 TC1724 .....	39
<b>GWM</b> .....	<b>40</b>
EDC17C53 TC1767 Version 1.....	40
EDC17C53 TC1767 Version 2.....	40
<b>Haval</b> .....	<b>41</b>
EDC17C53 TC1767 Version 1.....	41
EDC17C53 TC1767 Version 2.....	41
<b>Hino</b> .....	<b>42</b>
EDC17CV54 TC1767 .....	42



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.  
Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

<b>Honda</b> .....	<b>43</b>
EDC17CP06 TC1792 .....	43
<b>Isuzu</b> .....	<b>44</b>
EDC17C63 TC1724 .....	44
<b>Iveco</b> .....	<b>45</b>
EDC17C69 TC1793 Version 1.....	45
EDC17C69 TC1793 Version 2.....	45
EDC17C69 TC1793 Version 3.....	45
<b>JAC</b> .....	<b>46</b>
EDC17C53 TC1767 Version 1.....	46
EDC17C53 TC1767 Version 2.....	46
<b>Jeep</b> .....	<b>47</b>
EDC17C69 TC1793 Version 1.....	47
EDC17C69 TC1793 Version 2.....	47
EDC17C69 TC1793 Version 3.....	47
<b>JLR</b> .....	<b>48</b>
EDC17CP11 TC1796 .....	48
EDC17CP42 TC1797 .....	48
MED17.0 TC1767 .....	48
MED17.8.31 TC1797 .....	49
MEDC17.9 TC1793 .....	49
<b>JMC</b> .....	<b>50</b>
EDC17C63 TC1724 .....	50



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

<b>KIA/Hyundai .....</b>	<b>51</b>
DCU17PC43 TC1724.....	51
EDC17C08 TC1766 Version 1.....	51
EDC17C08 TC1766 Version 2.....	51
EDC17C53 TC1767 Version 1.....	52
EDC17C53 TC1767 Version 2.....	52
EDC17C57 TC1793 Version 1.....	52
EDC17C57 TC1793 Version 2.....	53
EDC17CP14 TC1796 Version 1 .....	53
EDC17CP14 TC1796 Version 2 .....	53
ME17.9.1 TC1796 .....	54
MEG17.9.22 TC1724 .....	54
<b>Mahindra.....</b>	<b>55</b>
EDC17C53 TC1767 Version 1.....	55
EDC17C53 TC1767 Version 2.....	55
EDC17C63 TC1724 .....	55
<b>Massey Ferguson .....</b>	<b>56</b>
EDC17C63 TC1724 .....	56
<b>Mercedes-Benz .....</b>	<b>57</b>
DCU17PC01 TC1766.....	57
DCU17PC42 TC1724.....	57
EDC17C42 TC1767 .....	57
EDC17C43 TC1797 .....	58
EDC17CP10 TC1796 .....	58



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17CP46 TC1797 .....	58
EDC17CP57 TC1793 Version 1 .....	59
EDC17CP57 TC1793 Version 2 .....	59
MED17.7.1 TC1797 Version 1 .....	59
MED17.7.1 TC1797 Version 2 .....	60
MED17.7.3.1 TC1797 .....	60
MED17.7.5 TC1793 .....	60
MED17.7.7 TC1793 Version 1 .....	61
MED17.7.7 TC1793 Version 2 .....	61
<b>MG .....</b>	<b>62</b>
EDC17C53 TC1767 Version 1.....	62
EDC17C53 TC1767 Version 2.....	62
<b>Mitsubishi Fuso.....</b>	<b>63</b>
EDC17CV54 TC1767 .....	63
<b>Nissan.....</b>	<b>64</b>
DCU17PC42 TC1724.....	64
EDC17C42 TC1767 .....	64
EDC17C84 TC1782 .....	64
<b>Opel .....</b>	<b>65</b>
EDC17C18 TC1766 .....	65
EDC17C19 TC1792 .....	65
EDC17C42 TC1767 .....	65
EDC17C69 TC1793 Version 1.....	66
EDC17C69 TC1793 Version 2.....	66





**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

EDC17C69 TC1793 Version 3.....	66
EDC17C84 TC1782 .....	67
<b>Peugeot.....</b>	<b>68</b>
EDC17CP11 TC1796 .....	68
ME17.9.53 TC1782.....	68
MED17.4.4 TC1793 .....	68
<b>Polaris .....</b>	<b>69</b>
M17.8.7 TC1762 .....	69
ME17.9.74 TC1767.....	69
<b>Renault.....</b>	<b>70</b>
DCU17PC42 TC1724.....	70
EDC17C42 TC1767 .....	70
EDC17C84 TC1782 .....	70
<b>Smart.....</b>	<b>71</b>
ME17.7.20 TC1782 Version 1.....	71
ME17.7.20 TC1782 Version 2.....	71
<b>SsangYong .....</b>	<b>72</b>
MED17.9.32 TC1782 .....	72
<b>Suzuki.....</b>	<b>73</b>
EDC17C69 TC1793 Version 1.....	73
EDC17C69 TC1793 Version 2.....	73
EDC17C69 TC1793 Version 3.....	73
ME17.9.5 TC1762 .....	74



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

ME17.9.51 TC1762.....	74
ME17.9.6 TC1767 .....	74
ME17.9.64 TC1724.....	75
<b>Toyota .....</b>	<b>76</b>
EDC17CP07 TC1766 .....	76
EDC17CP37 TC1766 .....	76
ME17.9.52 TC1782.....	76
ME17.9.53 TC1782.....	77
<b>VAG .....</b>	<b>78</b>
EDC17C46 TC1767 .....	78
EDC17C54 TC1797 .....	78
EDC17C64 TC1797 .....	78
EDC17C74 TC1793 Version 1.....	79
EDC17C74 TC1793 Version 2.....	79
EDC17CP14 TC1796 Version 1 .....	79
EDC17CP14 TC1796 Version 2 .....	80
EDC17CP20 TC1796 .....	80
EDC17CP44 TC1797 .....	80
EDC17U01 TC1766.....	81
INVCON 2.3 TC1797 .....	81
ME17.5.22 TC1724.....	81
ME17.5.24 TC1724.....	82
ME17.5.26 TC1724.....	82
ME17.5.6 TC1767 .....	82
MED17.1 TC1796 .....	83



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

MED17.1.21 TC1793 Version 1 .....	83
MED17.1.21 TC1793 Version 2 .....	83
MED17.1.27 TC1793 .....	84
MED17.1.6 TC1797 Version 1 .....	84
MED17.1.6 TC1797 Version 2 .....	84
MED17.5 TC1766 .....	85
MED17.5.1 TC1796 .....	85
MED17.5.2 TC1767 .....	85
MED17.5.20 TC1766 .....	86
MED17.5.21 TC1782 .....	86
MED17.5.25 TC1782 .....	86
MED17.5.5 TC1766 .....	87
<b>Valtra .....</b>	<b>88</b>
EDC17C63 TC1724 .....	88
EDC17CV54 TC1767 .....	88
<b>VAZ/UAZ .....</b>	<b>89</b>
ME17.9.7 TC1762 Version 1 .....	89
ME17.9.7 TC1762 Version 2 .....	89
<b>Volvo .....</b>	<b>90</b>
MED17.0 TC1767 .....	90
<b>Yanmar .....</b>	<b>91</b>
EDC17CV54 TC1767 .....	91




**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Alfa Romeo


### EDC17C69 TC1793 Version 1



### EDC17C69 TC1793 Version 2



### EDC17C69 TC1793 Version 3







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Ashok leyland

### EDC17CV54 TC1767






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Aston Martin

### ME17.8.31 TC1797






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## BAJAJ KTM

### M17.8.42 TC1762






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## BAW

### EDC17CV54 TC1767








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## BMW


### DCU17PC42 TC1724



### EDC17C06 TC1766



### EDC17C41 TC1797








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17C50 TC1797



### EDC17C76 TC1793



### EDC17CP02 TC1766







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17CP09 TC1796



### EDC17CP45 TC1797 Version 1



### EDC17CP45 TC1797 Version 2







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17CP49 TC1797



### ME(V)17.2.1 TC1796



### MEV17.2 TC1766







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### MEVD17.2 TC1797



### MEVD17.2.3 TC1793



Ground
  Power
  Can-H
  Can-L
  GPT-1
  GPT-2



**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## BMW Motorrad

### ME17.2 TC1797



### ME17.2.4 TC1793






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## BRP

### ME17.8.5 TC1762






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## CFMoto

### ME17.8.10 TC1728








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## China

### ME17.6.8 TC1762



### ME17.8.8/17.8.8.1/17U6/UP6 TC1728/1782






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.



Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Citroen



### EDC17CP11 TC1796



### ME17.9.53 TC1782



### MED17.4.4 TC1793






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Claas

### EDC17C53 TC1767 Version 1



### EDC17C53 TC1767 Version 2






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.



Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Dacia

### EDC17C42 TC1767



### EDC17C84 TC1782






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Deutz



### EDC17C53 TC1767 Version 1



### EDC17C53 TC1767 Version 2



### EDC17CV54 TC1767






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.



Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## DongFeng



### EDC17C63 TC1724



### EDC17CV54 TC1767



### MED17.4.4 TC1793






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Doosan

### EDC17CV54 TC1767






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Farmtrac

### EDC17C63 TC1724








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Fiat


### EDC17C69 TC1793 Version 1



### EDC17C69 TC1793 Version 2



### EDC17C69 TC1793 Version 3








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### EDC17C84 TC1782






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.



Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Ford



### DCU17PC43 TC1724



### EDC17C10 TC1797



### EDC17C70 TC1793







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### MED17.0 TC1767



### MED17.0.1 TC1767 Version 1



### MED17.0.1 TC1767 Version 2







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### MEDG17.0 TC1797






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Foton

### EDC17C63 TC1724






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Great Wall


### EDC17C53 TC1767 Version 1



### EDC17C53 TC1767 Version 2



### EDC17C63 TC1724







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## GWM

### EDC17C53 TC1767 Version 1



### EDC17C53 TC1767 Version 2









**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Haval

### EDC17C53 TC1767 Version 1



### EDC17C53 TC1767 Version 2






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Hino

### EDC17CV54 TC1767






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Honda

### EDC17CP06 TC1792






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Isuzu

### EDC17C63 TC1724






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Iveco


### EDC17C69 TC1793 Version 1



### EDC17C69 TC1793 Version 2



### EDC17C69 TC1793 Version 3







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## JAC

### EDC17C53 TC1767 Version 1



### EDC17C53 TC1767 Version 2






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Jeep


### EDC17C69 TC1793 Version 1



### EDC17C69 TC1793 Version 2



### EDC17C69 TC1793 Version 3






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## JLR


### EDC17CP11 TC1796



### EDC17CP42 TC1797



### MED17.0 TC1767











**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### MED17.8.31 TC1797



### MEDC17.9 TC1793






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## JMC

### EDC17C63 TC1724





**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## KIA/Hyundai


### DCU17PC43 TC1724



### EDC17C08 TC1766 Version 1



### EDC17C08 TC1766 Version 2








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17C53 TC1767 Version 1



### EDC17C53 TC1767 Version 2



### EDC17C57 TC1793 Version 1








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17C57 TC1793 Version 2



### EDC17CP14 TC1796 Version 1



### EDC17CP14 TC1796 Version 2








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### ME17.9.1 TC1796



### MEG17.9.22 TC1724







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Mahindra


### EDC17C53 TC1767 Version 1



### EDC17C53 TC1767 Version 2



### EDC17C63 TC1724






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Massey Ferguson

### EDC17C63 TC1724








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Mercedes-Benz



### DCU17PC01 TC1766



### DCU17PC42 TC1724



### EDC17C42 TC1767









**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17C43 TC1797



### EDC17CP10 TC1796



### EDC17CP46 TC1797






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17CP57 TC1793 Version 1



### EDC17CP57 TC1793 Version 2



### MED17.7.1 TC1797 Version 1








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### MED17.7.1 TC1797 Version 2



### MED17.7.3.1 TC1797



### MED17.7.5 TC1793







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### MED17.7.7 TC1793 Version 1



### MED17.7.7 TC1793 Version 2






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## MG

### EDC17C53 TC1767 Version 1



### EDC17C53 TC1767 Version 2






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Mitsubishi Fuso

### EDC17CV54 TC1767





**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.



Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Nissan



### DCU17PC42 TC1724



### EDC17C42 TC1767



### EDC17C84 TC1782









**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Opel



### EDC17C18 TC1766



### EDC17C19 TC1792



### EDC17C42 TC1767







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17C69 TC1793 Version 1



### EDC17C69 TC1793 Version 2



### EDC17C69 TC1793 Version 3







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### EDC17C84 TC1782






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Peugeot


### EDC17CP11 TC1796



### ME17.9.53 TC1782



### MED17.4.4 TC1793






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Polaris

### M17.8.7 TC1762



### ME17.9.74 TC1767








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.



Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Smart

### ME17.7.20 TC1782 Version 1



### ME17.7.20 TC1782 Version 2







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## SsangYong

### MED17.9.32 TC1782








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Suzuki


### EDC17C69 TC1793 Version 1



### EDC17C69 TC1793 Version 2



### EDC17C69 TC1793 Version 3








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.



### ME17.9.5 TC1762



### ME17.9.51 TC1762



### ME17.9.6 TC1767






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### ME17.9.64 TC1724






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Toyota



### EDC17CP07 TC1766



### EDC17CP37 TC1766



### ME17.9.52 TC1782







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### ME17.9.53 TC1782






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.



Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## VAG



### EDC17C46 TC1767



### EDC17C54 TC1797



### EDC17C64 TC1797









**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17C74 TC1793 Version 1



### EDC17C74 TC1793 Version 2



### EDC17CP14 TC1796 Version 1







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.



### EDC17CP14 TC1796 Version 2



### EDC17CP20 TC1796



### EDC17CP44 TC1797









**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### EDC17U01 TC1766



### INVCON 2.3 TC1797



### ME17.5.22 TC1724







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### ME17.5.24 TC1724



### ME17.5.26 TC1724



### ME17.5.6 TC1767







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.


### MED17.1 TC1796



### MED17.1.21 TC1793 Version 1



### MED17.1.21 TC1793 Version 2









**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.



### MED17.1.27 TC1793



### MED17.1.6 TC1797 Version 1



### MED17.1.6 TC1797 Version 2








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.



### MED17.5 TC1766



### MED17.5.1 TC1796



### MED17.5.2 TC1767








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.



### MED17.5.20 TC1766



### MED17.5.21 TC1782



### MED17.5.25 TC1782







**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

### MED17.5.5 TC1766






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Valtra

### EDC17C63 TC1724



### EDC17CV54 TC1767








**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.


Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## VAZ/UAZ

### ME17.9.7 TC1762 Version 1



### ME17.9.7 TC1762 Version 2






**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Volvo

### MED17.0 TC1767





**Attention!** Any incorrect actions with engine and transmission control units can lead to their failure. You are using BitBox software at your own risk.

Our team is not responsible for data loss, damages, loss of profits or any other kind of loss while using (or misusing) BitBox software.

## Yanmar

### EDC17CV54 TC1767

